

Attachment I - Lead in Water Sample Results Summary

School Name: Glenview Elementary School

Outlet Code	Sample ID	Location/Description	Result (ppb)	Above AL?
1	38-1230-G01	APR girls bathroom; sink	2.36	No
2	38-1230-G02	APR boys bathroom; sink	2.68	No
3	38-1230-G03	Hall by Room 118; water fountain	ND	No
4	38-1230-G04	Nurse's office; sink	1.27	No
5	38-1230-G05	Nurse's office restroom; sink	2.26	No
6	38-1230-G06	Teachers Lounge; sink	1.18	No
7	38-1230-G07	Teachers Lounge restroom; sink	1.30	No
8	38-1230-G08	Hall by Room 111; water fountain	ND	No
9	38-1230-G09	Girls restroom by Room 118; sink (middle)	1.45	No
10	38-1230-G10	Room 106; sink	5.29	No
11	38-1230-G11	Boys restroom by Room 103; sink (left)	1.90	No
12	38-1230-G12	Room 103; sink	3.31	No
13	38-1230-G13	Room 103 restroom; sink	7.45	No
14	38-1230-G14	Hall by Room 102; water fountain	2.27	No
15	38-1230-G15	Room 101; water fountain	4.6	No
16	38-1230-G16	Room 101 restroom; sink	1.90	No
17	38-1230-G17	Room 100; sink	4.05	No
18	38-1230-G18	Room 100 restroom; sink	19.2	Yes
19	38-1230-G19	Boys restroom by Room 122 sink (left)	14.1	No
20	38-1230-G20	Hall by Custodial Closet; water fountain	ND	No

Action Level (AL) ≥ 15.5 parts per billion (ppb)

Attachment C - Drinking Water Outlet Inventory

School: Glenview Elementary School		Address:										
Grade Levels: K-12	Year Constructed:	Year of Renovations/Additions:										
Outlet Code ¹	Location/Description	Sample #	Operating ² (Y/N)	Corrosion ¹ (Y/N)	Filter ⁴ (Y/N)	Brass ⁵ (Y/N)	Aerator/ Screen	Motion Activated	Chiller (Y/N)	Water Cooler		
											Make	Model
1	APR girls bathroom; sink	38-1230-G01	X	N	N	X	X	N	N			
2	APR boys bathroom; sink	38-1230-G02	X	N	N	X	X	N	N			
3	Hall by Room 118; water fountain	38-1230-G03	X	N	N	X	N	N	N			
4	Nurse's office; sink	38-1230-G04	X	N	N	X	X	N	N			
5	Nurse's office restroom; sink	38-1230-G05	X	N	N	X	X	N	N			
6	Teachers Lounge; sink	38-1230-G06	X	N	N	X	X	N	N			
7	Teachers Lounge restroom; sink	38-1230-G07	X	N	N	X	X	N	N			
8	Hall by Room 111; water fountain	38-1230-G08	X	N	N	X	N	N	N			
9	Girls room by Room 118; sink (middle)	38-1230-G09	X	N	N	X	N	N	N			
10	Room 106; sink	38-1230-G10	X	N	N	X	X	N	N			
11	Boys restroom by Room 103; sink (left)	38-1230-G11	X	N	N	X	X	N	N			
12	Room 103; sink	38-1230-G12	X	N	N	X	X	N	N			
13	Room 103 restroom; sink	38-1230-G13	X	N	N	X	X	N	N			
14	Hall by Room 102; water fountain	38-1230-G14	X	N	N	X	N	N	N			
15	Room 101; water fountain	38-1230-G15	X	N	N	X	N	N	N			
16	Room 101 restroom; sink	38-1230-G16	X	N	N	X	X	N	N			
17	Room 100; sink	38-1230-G17	X	N	N	X	X	N	N			
18	Room 100 restroom; sink	38-1230-G18	X	N	N	X	X	N	N			
19	Boys restroom by Room 122 sink (left)	38-1230-G19	X	N	N	X	X	N	N			
20	Hall by Custodial Closet; water fountain	38-1230-G20	X	N	N	X	N	N	N			


¹ Number outlets starting at the closest outlet to the Point of Entry (POE)

² Document if permanently or temporarily out of service on the Attachment B- Plumbing Profile

³ Signs of corrosion detected, such as but not limited to leaks, rust-colored water, or stained fixtures

⁴ Document on Attachment D- Filter Inventory

⁵ Indicated if any fittings, faucets or valves are brass


 Michelle Dwyer
 5/26/17

Individual School Project Officer Name, Signature & Date:

